EAST Search History

Ref #	Hits	Search Query	DBs	Default Operator	Plurals	Time Stamp
L7	101	((ink\$2jet (ink adj2 jet)) and (print\$2head (print adj2 head))) and ((driv\$3 pulse) adj2 (wave waveform pulse)) with (measur\$3 calculat\$3) and (347/6,11,7,10,19. ccls. "358".clas.)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/06/11 15:38
L8	27	(inspecting adj ink) and (waveform pulse wave-form (wave adj form)) and (inkjet ink-jet (ink adj jet)) and (correct\$ adjust\$ alter\$)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/06/11 15:38
L9	76	347/10.ccls. and ((equation formula) same (waveform wave-form (wave adj form)) ((waveform wave-form (wave adj form)) same (correcting adjusting adjust)))	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/06/11 15:38
L10	27	((print printing) with test) same (waveform wave-form (wave adj form)) with (driving drive)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/06/11 15:38
L11	17	347/100.ccls. and (dye dyeing dying) same ink same (test inspection inspecting testing) same (base standard)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/06/11 15:38
L12	24	(ink) and (correct\$ adjust\$ alter\$) with (waveform pulse wave-form (wave adj form)) and (inkjet ink-jet (ink adj jet)) and 347/19.ccls. and (measure measuring detect detecting sensing sense) with (waveform wave-form pulse (wave adj form)) and (formula equation) and (driving with voltage)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/06/11 15:38
L13	63	((ink\$2jet (ink adj2 jet)) and (print\$2head (print adj2 head))) and ((driv\$3 pulse) adj2 (wave waveform pulse)) with (determine) and (347/6,11,7,10,19.ccls. "358". clas.)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/06/11 15:39
L14	35	((ink\$2jet (ink adj2 jet)) and (print\$2head (print adj2 head))) and ((driv\$3) adj2 (wave waveform)) with (measur\$3 calculat\$3 determine) and (347/6,11,7,10,19. ccls. "358".clas.)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/06/11 15:40